Oil Field Environmental Incident Summary

Responsible Party: Zargon (ND) Oil & Gas **Well Operator:** ZARGON OIL (ND) INC.

Well Name: TRURO MADISON UNIT

Field Name: TRURO Well File #:

Date Incident:10/28/2015Time Incident:07:00Facility ID Number:405944-01County:RENVILLETwp:160Rng:84Sec:27Qtr:NW NW

Location Description: Oil sprayed out of treater gasket and put about 5 bbls of oil inside dike and

about 3 bbls on turnaround at TB location. It also sprayed light film on farmers

land by CTB about 100 yards SE of tunaround. F

Submitted By: Roger Erickson Received By:

Contact Person: Daryl Harrison

700 333 5TH AVE SW CALGARY, AB T2P 3B6

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1713 Feet

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No Reported to NRC: Yes

Spilled Units Recovered Units Followup Units

Oil 8 Barrels 8 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

No risk to environment or people with no health risk

Areal Extent:

Potential Environmental Impacts:

No impact to water, groundwater and very small impact to soil

Action Taken or Planned:

Oil was cleaned up and put in rolloff contaniner to be hauled to waste dispoal, gravel is spread inside dike and around turnaround and gaskets will be changed on treater.

Wastes Disposal Location: It will be hauled away to waste disposal factility

Agencies Involved:

Updates

Date: 11/3/2015 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, release impacted area off location. Further followup required.

Date: 12/17/2015 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:20. 14 degrees F, cloudy, W/NW wind 10-20 mph. Observed the site and took photos. Walked heater/treater areas, CTB turnaround location, tank battery location and CRP land adjacent to the property. Did not notice any petroleum impacts to areas around the CTB; however, there was an approximate 30' by 15' area of soil and vegetation below and west of the flare stack that appeared impacted by petroleum product. Not sure if this is the area reported or another release not yet reported. Further followup needed.